


KEY

- Site Boundary and Proposed Turbine Locations
- Study Area Radius
- Consented / Under Construction Wind Farms

Wind farms theoretically visible

- Cumberhead West Wind Farm visible only
- Broken Cross, Broken Cross (small turbines) and/or M74 Eco-Park visible only
- Cumberhead West Wind Farm and Broken Cross, Broken Cross (small turbines) and/or M74 Eco-Park visible



Cumberhead West Wind Farm
Environmental Impact Assessment Report
Figure 6.32 - Cumulative ZTV with Broken Cross, Broken Cross (small turbines) and M74 Eco-Park

Date:	29/10/2020	Drawn by:	EK	Checked by:	DT/DG	Version:	A
-------	------------	-----------	----	-------------	-------	----------	---

P19-2443.036